



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Art Unit

3661

Applicant

Robert R. Turnbull et al.

Appln. No.

09/827,304

Filing Date : Confirmation No.:

April 5, 2001 4135

For

VEHICLE REARVIEW MIRROR ASSEMBLY INCORPORATING A

COMMUNICATION SYSTEM

Assistant Commissioner for Patents

Box Missing Part

Washington, D.C. 20231

Attention: Official Draftsperson

-30-2001

TRANSMITTAL OF NEW DRAWINGS TO CORRECT INFORMALITIES

In response to the Notice to File Missing Parts of Nonprovisional Application mailed June 4, 2001, Applicants request that the enclosed 24 sheets of corrected formal drawings be entered in the above-identified application. The suggested corrections have been incorporated in the drawings.

Respectfully submitted,

ROBERT R. TURNBULL ET AL.

By:

Price, Heneveld, Cooper,

DeWitt & Litton

Date

Terry & Callaghan

Registration No. 34 559

695 Kenmoor, S.E.


Post Office Box 2567


Grand Rapids, Michigan 49501


(616) 949-9610

TSC/rsw

The first form fault fault fault form is a second of the fault fault fault fault fault fault fault fault fault















Fig. 6


























FIG. 7D


0 149 149 16<u>4</u> 302 FIG. 8A 162a Ø 164 149 303 149 160a


.30a














Fig. 17




Fig. 18